
SURVEY PLAT

NO. 11700 CHAUCER DRIV	E ; IN THE CITY OF	FRISCO	, TEXAS, DESCRIBED AS	S FOLLOWS:
LOT NO. 3 BLOCK NO.	K 0F	PARKSIDE ESTAT	ES NO. 2	
AN ADDITION TO THE	CITY OF FRISCO	сош	n county, texas accordi	NG TO THE
PLAT THEREOF RECORDED IN	OLUME N AT P	AGE 702 OF THE LAF	RECORDS OF COLLIN COU	hiy, texas.
DELONIC DASIS NOTE: THE READINGS SH	OWN HEREON ARE RASED ON T	HE ABOVE-REFERENCED, RECO	rded hap or plat.	
C.I.= CONTROLLING MONUMENT, F.I.R.= FOUND IRON ROD; S.I.R.= SET IRON ROD; F.I.P.= FOUND IRON PIPE; F.C.P.= FENCE CORNER POST. ALL SET IRON RODS ARE 1/2" DAMETER WITH YELLOW CAP STAMPED "ARTHUR SURVEYING COMPANY".				
ALL IRON RODS ARE 1/2" DIAMETER UN	LESS OTHERWISE NOTED.			



TO THE LIENHOLDERS AND/OR THE DYNERS OF THE PREMISES SURVEYED AND TO CHICAGO TITLE CO. GF# 8007225 THE UNDERSIGNED DOES HEREDY CERTIFY THAT THIS SURVEY WAS THIS DAY MADE ON THE GROUND OF THE PROPERTY LEGALLY DESCRIBED HEREON AND IS CORRECT, AND, TO THE BEST OF MY KNOWLEDGE, THAT THERE ARE NO VISIBLE DISCREPANCIES, CONFLICTS, SHORTAGES IN AREA, BOUNDARY LINE CONFLICTS, ENCROACHMENTS, OVERLAPPING OF IMPROVEMENTS, EASEMENTS OR RIGHT OF WAY THAT I HAVE BEEN ADVISED OF EXCEPT AS SHOWN HEREON, AND THAT SND PROPERTY HAS ACCESS TO AND FROM A DEDICATED ROADWAY. IS NOT _ WITHIN A SPECIAL FLOOD HAZARO AREA FLOOD NOTE: IT IS MY OPINION THAT THE PROPERTY DESCRIBED HEREIN_ ACCORDING TO THE FEDERAL ENERGENCY MANGEMENT AGENCY FLOOD INSURANCE RATE MAP COMMUNITY-PANEL NO. 480134 0270 G.
PRESENT EFFECTIVE DATE OF MAP JANUARY 19, 1996, HEREN PROPERTY STUATED WITHIN ZONE ______X (UNSHADED)

DATE: 09-10-2004 SCALE: 1" = 20' AS.C. NO.: G2406101 DRAWN BY: K.B.W. CHECKED

ARTHUR 'SURVEYING COMPANY, INC. Registered Professional Lond Surveyors P.O.Box 54 - Leufsville, Texas 75067 Office: (972) 221-4675 Fax: (972) 221-4675

REGISTERED PROFESSIONAL LAND STRIKEYOR

CRYSTAL ROBERTSO

WSURVE